

SAFETY NOTICE powerCON® TRUE1 TOP

Please regularly check the condition of your powerCON TRUE1 TOP connector system (cable connector & chassis) for clear signs of wear and tear.

Through improper use and the excessive use of force, the encoding lugs and guide slots in the connector system can become so severely worn or damaged that it is possible to insert the cable connector the wrong way. However, when inserted the wrong way, the cable connector should not twist-lock into place.

A cable connector/plug connector inserted the wrong way could, in some circumstances, lead to contact between live wires and the grounding contact in the plug socket.

To determine that the cable connector/plug connector is inserted correctly, follow the use instructions and listen for the "click" when performing the twist-lock. Immediately unplug any connector that does not twist-lock correctly in place.



When connecting, match the notch on the cable connector to the corresponding guide slot on the chassis.



Note:
After inserting properly as in illustration A, twist the cable connector clockwise to lock.





Note: The proper twist-lock is achieved when the silvery tab is in the position shown in **C** and an audible «click» is heard.





SAFETY WARNING

incorrect insertion may cause electrical contact misalignment resulting in equipment malfunction and/orpersonalinjury.

The manufacturer of cord sets and of interconnection cord sets is responsible for the conformity assessment according to the applicable regulatory documents.



Draft. Nr.: BDA 559 V3 Update: 2023-06-28

Neutrik AG | LI-9494 Schaan

www.neutrik.com

ALL RIGHTS RESERVED.

Data subject to change without prior notice. © 2023 NEUTRIK®. NEUTRIK®, powerCON are registered trademark of Neutrik AG.





SAFETY NOTICE powerCON® TRUE1 TOP





nax. 1 Newton

Note:

When connecting, match the notch on the plug connector to the corresponding guide slot on the chassis.



Note:

After inserting properly as in illustration (A), twist the plug connector clockwise to lock.









Note:

The proper twistlock is achieved when the silvery tab is in the position shown in **©** and an audibel «click» is heard.





SAFETY WARNING

incorrect insertion may cause electrical contact misalignment resulting in equipment malfunction and/orpersonalinjury.



Note:

When connecting, match the notch on the cable connector to the corresponding guide slot on the plug connector.



B

Note:

After inserting properly as in illustration (A), twist the cable connector clockwise to lock.



G







Note:

The proper twistlock is achieved when the silvery tab is in the position shown in c and an audibel «click» is heard.





SAFETY WARNING

incorrect insertion may cause electrical contact misalignment resulting in equipment malfunction and/orpersonal injury.

The manufacturer of appliance connection cables and of further connection appliance connection cables is responsible for the conformity assessment according to the applicable directives and standards.



Draft. Nr.: BDA 559 V3 Update: 2023-06-28

Neutrik AG | LI-9494 Schaan

www.neutrik.com



Data subject to change without prior notice. © 2023 NEUTRIK®. NEUTRIK®, powerCON are registered trademark of Neutrik AG.

ALL RIGHTS RESERVED.