




ASSEMBLY INSTRUCTION

SHIELD-SPREADING-TOOL



How to use the "SHIELD-SPREADING-TOOL"

- Take the prepared cable into your left hand and the shield-spreading-tool between your fingers of your right.
- Position the straight wire-parts of the clamp over the screen at the end of the jacket, you can use the jacket as a block-shoulder.
- Press the tool with your fingers together and turn the cable around. You will see that the screen get spread off easily and does not effect the foil at all.

NEUTRIK AG
NEUTRIK Zürich AG
NEUTRIK USA Inc.
NEUTRIK (UK) Ltd.

LI T: +423 / 237 24 24 F: +423 / 232 53 93
CH T: +41 44 / 736 5010 F: +41 44 / 736 5011
USA T: +1 732 / 901 9488 F: +1 732 / 901 9608
UK T: +44 1983 / 811 441 F: +44 1983 / 811 439

NEUTRIK Vertriebs GmbH
NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.

DE/NL/AT T: +49 8131 / 280 890 F: +49 8131 / 280 830
FR T: +33 1 / 4131 6750 F: +33 1 / 4131 0511
JP T: +81 3 / 3663 4733 F: +81 3 / 3663 4796
HK T: +852 / 2687 6055 F: +852 / 2687 6052

Draft. Nr.: 3102M0791 | Update: 02.04.2009 | Data subject to change without prior notice. ©2009 NEUTRIK®. ALL RIGHTS RESERVED.

www.neutrik.com

NEUTRIK