# XIRIUM PRO

XIRIUM PRO App & Firmware

**Version history** - Issues & solutions

NEUTRIK®

| Firmware on XIRIUM PRO device | | App |
|---|---|---|
| **App Control firmware NACF-Dec052014** *released in December, 2015*<br><br>- Initial release | **XIRIUM PRO firmware 1.0** *released in December, 2015*<br><br>- Initial release | **XIRIUM PRO app 1.0** *released in December, 2015*<br><br>- Initial release |
| | **XIRIUM PRO firmware 1.1** *released in February, 2016*<br><br>- Packet-loss indication<br>- Unlink support<br><br>**XIRIUM PRO firmware 1.2** *released in February, 2016*<br><br>- Bug fix | **XIRIUM PRO app 1.1** *released in February, 2016*<br><br>- Monitoring signal strength and packet-loss<br>- Unlink RX from TX; dragging to "available devices" |
| **App Control firmware NACF-Oct222015** *released in April, 2016*<br><br>- Bug Fix | **XIRIUM PRO firmware 2.0** *released in April, 2016*<br><br>- Mute on RX<br>- Country specific settings<br>- Optimized battery algorithm and display<br>- Optimized RSSI display | **XIRIUM PRO app 2.0** *released in April, 2016*<br><br>- Mute switch in RX EDIT mode<br>- Country specific settings / Touring-option<br>- Optimized battery algorithm and display<br>- Optimized RSSI display |
| | **XIRIUM PRO firmware 2.1** *released in August, 2016*<br><br>- Bug fix | **XIRIUM PRO app 2.1** *released in August 2016*<br><br>- Bug fix<br>- UAE included in zone 3 |
| | | **XIRIUM PRO app 2.1.1** *released in September, 2016*<br><br>**only an iOS release!**<br><br>- iOS 10 compatible |
| **App Control firmware NACF-Aug122016** *released in February, 2017*<br><br>- Bug Fix<br><br>Latest version! | **XIRIUM PRO firmware 3.0** *released in February, 2017*<br><br>- Advanced Mode<br>- Device Temperature Indication | **XIRIUM PRO app 3.0** *released in February, 2017*<br><br>- RF Attenuator<br>- Hide SSID option<br>- Device Temperature Indication<br>- Bug fixes<br>- Australia, New Zealand, Hong Kong included in zone 2 |

| Firmware on XIRIUM PRO device | | App |
|---|---|---|
| | **XIRIUM PRO firmware 3.1**<br>*released in June, 2017*<br><br>- Bug fixes<br>- Optimizations<br>- Adjusted Hardware Reset (sets attenuator to off) | **XIRIUM PRO app 3.1**<br>*released in June, 2017*<br><br>- support for FW 3.1 |
| | **XIRIUM PRO firmware 3.2**<br>*released in October, 2017*<br><br>- Major Bug fixes<br>- Optimizations<br><br>Latest version! | **XIRIUM PRO app 3.2**<br>*released in October, 2017*<br><br>- support for FW 3.2<br>- iOS 11 compatible<br>- Mounting Guide update<br><br>Latest version! |

Neutrik strongly recommends to keep the devices and the app up-to-date!
Since App version 2.0 and FW version 2.0 every FW update will be communicated to users via the app. The user will be informed by the app store / play store if there is a new app version available. If the user downloads the latest app but uses an old firmware on the device there will be a message in the app with a recommendation to update the devices to make use of all the new features in the app.